

W2017050201

/

1

2

3

4

5

48

6

:

0898-88382756

0898-88380003

2

5

		/	
			0898-88812752
		/	2017.5.2

1

2017 5 12

1

GB3838-2002

3 5

1

1		GB/T5750. 12-2006	2. 3	
2		GB/T5750. 12-2006	1. 1	
3		GB/T5750. 12-2006	2. 3	
4		GB/T5750. 12-2006	4. 3	
5		GB/T5750. 6-2006	6. 1	
6		GB/T5750. 6-2006	9. 1	
7		GB/T5750. 6-2006	10. 1	
8		GB/T5750. 6-2006	11. 1	
9		GB/T5750. 6-2006	8. 1	
10		GB/T5750. 6-2006	7. 3	
11		GB/T5750. 5-2006	4. 2	-
12		GB/T5750. 5-2006	3. 2	
13		GB/T5750. 5-2006	5. 3	
14		GB/T5750. 4-2006	1. 1	-
15		GB/T5750. 4-2006	2. 1	-
16		GB/T5750. 4-2006	3. 1	
17		GB/T5750. 4-2006	4. 1	
18	PH	GB/T5750. 4-2006	5. 1	
19		GB/T5750. 6-2006	1. 1	S
20		GB/T5750. 6-2006	2. 2	
21		GB/T5750. 6-2006	3. 2	
22		GB/T5750. 6-2006	4. 2. 1	
23		GB/T5750. 6-2006	5. 1	
24		GB/T5750. 5-2006	2. 2	
25		GB/T5750. 5-2006	1. 2	
26		GB/T5750. 4-2006	8. 1	
27		GB/T5750. 4-2006	7. 1	
28		GB/T5750. 7-2006	1. 1	
29		GB/T5750. 4-2006	9. 1	4-
30		GB/T5750. 4-2006	10. 2	
31		GB/T5750. 5-2006	9. 1	
32				
33				
34		GB/T 5750. 8 2006	1. 2	
35		GB/T 5750. 8 2006	1. 2	

1

		GB3838-2002() ()	
			W17050201
1		(MPN/100mL)	>2419.6
2		(CFU/mL)	95
3		1000 (MPN/100mL)	50.4

4